

PRIMARY RECORD

Primary # _____

HRI _____

Trinomial # _____

NRHP Status Code _____

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 3

*Resource Name or # (Assigned by recorder) 5586 Broadway, Live Oak

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; _____ % of _____ % of Sec _____ ; B.M. _____

c. Address 5586 Broadway City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: 10-140-003

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The single-family residence at 5586 Broadway south of Live Oak was constructed in the circa 1920s in the Craftsman style. The building is moderately set back from the street. It is a farmhouse with associated ancillary buildings, and is located on the west side of Broadway between Bloyd and Sanders Roads. The house faces east within a rural farming environment with the Sutter Buttes visible in the background.

This is a one-story residence with a rectangular floor plan. The façade is asymmetrical and the building sits on a concrete foundation (with about a foot of height visible). The residence has a wood-framed structural system and an exterior clad in horizontal wood boards. The building is covered by a moderately-pitched, front-gabled roof clad with composition shingles. The moderately-overhanging eaves have exposed rafters. The building has one dormer on each of the southern and northern sides of the gabled roof. They are wide dormers with shed roofs clad with composition shingles. The wall surfaces of the dormers are clad in circa 1940s asbestos siding. Each dormer has four double-hung wood-sash windows with lamb tongues on the upper sash.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking northwest at the façade and south elevation, July 14, 2006

*P6. Date Constructed/Age and

Sources: Historic

Prehistoric Both

circa 1920s, visual observation

*P7. Owner and Address:

William A. Gruenthal

5420 Broadway Road

Live Oak, CA 95953

*P8. Recorded by: Name,

affiliation, and address) _____

Sharyl Simmons, volunteer

Galvin Preservation Associates Inc.

1611 S. Pacific Coast Hwy. Suite 104

Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe)

Intensive

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates, 2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record

Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record

Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 3

Recorded By: Sharyl Simmons ***Resource Name or #** (Assigned by recorder) 5586 Broadway, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

***P3a. Description:**

The primary entry is located at the façade. It consists of a partial-width porch located at the south end of the façade and sheltered by the principal roof. Its corner is supported by a simple wood post. Concrete steps lead up to the landing made of wood boards. The main entry consists of a Craftsman-style wood and glass door with a wood screen door. The secondary entry is likely located at the west (rear) elevation. There are three windows on the façade. There are two wood-sash picture windows at the first floor level of the façade. One is located within the porch. The attic level has a single wood-sash window with a single light; it is likely awning or hopper style. The other elevations have either paired or single double-hung wood-sash windows. All windows have wide casings and sills.

Landscaping elements include a lawn and several trees. Other features include a rock wall at the east border of the property and a white picket fence to the north of the residential boundary. There is an asphalt driveway leading to the back yard. Other features include a deteriorating shed located at the west (rear) of the property. There is also a two-car garage and storage building located to the west of the building.

The two first-story window sashes have been replaced. The condition of the building is good.

*Resource Name or # (Assigned by recorder)

5586 Broadway, Live Oak

Recorded By: Sharyl Simmons

Date: April, 2006 Continuation Update



View looking west at the façade



View looking northwest at the south elevation



View looking northwest at the south elevation and a shed located behind it



View looking northwest at the south elevation dormer



View looking northwest at a two-car garage and storage building located behind the residence

PRIMARY RECORD

Page 1 of 3

*Resource Name or # (Assigned by recorder) 9596 Broadway, Live Oak

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; _____ 1/4 of _____ 1/4 of Sec _____ ; _____ B.M.

c. Address 9596 Broadway City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN 06-261-022

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The single-family residence at 9596 Broadway in Live Oak was constructed in 1915 in the Craftsman style. It today houses two residential units. The building is located near the front of the parcel, on the west side of Broadway between Center Way and Apricot Street. The residence faces east within a residential neighborhood, located at the southern end of Broadway.

This is a two-story residence with an irregular floor plan. The façade is asymmetrical and the building sits on a concrete foundation. The residence has a wood-framed structural system and an exterior clad in horizontal wood siding. The building is covered by a side-gabled roof, with a low pitch on the front side and a steep pitch at the rear. The moderately-overhanging eaves have exposed rafters and the gable ends have purlins. There is also an additional low-pitched front gable at the north side of the façade. There is stickwork located within the gable. The roof is clad with composition shingles. The residence has one exterior brick chimney located on the north elevation.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking west at the façade, July 14, 2006

*P6. Date Constructed/Age and Sources: Historic Prehistoric Both
1915, Sutter County Assessor

*P7. Owner and Address:
Robertson Family Trust, et. al.
9596 Broadway
Live Oak, CA 95953

*P8. Recorded by: Name, affiliation, and address) _____
Phyllis Smith, volunteer
Galvin Preservation Associates Inc.
1611 S. Pacific Coast Hwy. Suite 104
Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe)
 Intensive
 Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates, 2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 3

Recorded By: Phyllis Smith ***Resource Name or #** (Assigned by recorder) 9596 Broadway, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

***P3a. Description:**

The primary entry is located at the façade. It consists of a partial-width porch sheltered by a dropped secondary shed roof clad with composition shingles. The roof extends to the south side of the façade where there is a one-story wing. Both ends of the shed roof have low-pitched gables with stickwork. There is another identical gable located at the façade side of the wing. The porch is supported by a square wood support clad in horizontal wood siding. Concrete steps lead up to the wood landing. The front door is wood and glass with eight window panes. There is a wood screen door. An exterior wood stairway with wood handrails, located on the south elevation, leads to the upstairs unit. It consists of a porch with a dropped secondary shed roof. The first floor windows consist of Craftsman style double-hung wood-sash windows. Two of these windows look onto the front porch. The second floor has double-hung wood-sash windows. There is a one-story square bay with a low-pitched gable with stickwork located at the north elevation. There is also one Craftsman-style single wood-sash casement window at the first floor of this elevation.

Landscaping elements include mature camellia plants, a front lawn and miscellaneous shrubs. There is a concrete walkway leading from the sidewalk to the front porch and the north side of the house. A garage located to the northwest of the house has an asphalt driveway. There is also a carport to the south of the house which fronts a dirt driveway.

The exterior stairway is not original. The condition of the building is good.

CONTINUATION SHEET

Page 3 of 3

*Resource Name or # (Assigned by recorder) 9596 Broadway, Live Oak

Recorded By: Phyllis Smith

Date: April, 2006 Continuation Update



View looking southwest at the north elevation



View looking northwest at the south elevation



View looking west at the façade porch detail

PRIMARY RECORD

Primary # _____
HRI _____

Trinomial # _____
NRHP Status Code _____

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 9892-9894 Broadway, Live Oak

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; _____ % of _____ % of Sec _____ ; B.M. _____

c. Address 9892-9894 Broadway City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: 06-177-003

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The commercial building at 9892-9894 Broadway in Live Oak was constructed in 1938 in the Spanish Colonial Revival style. The building is built up to the property line, and is located on the west side of Broadway between Gum and Fir Streets. It faces east within Live Oak's historic downtown area. The Sacramento Northern lines are located to the east.

This is a one-story rectangular building. The façade is symmetrical and the building sits on a concrete foundation. It has a wood-framed structural system and an exterior clad in smooth stucco. The building is covered by a flat roof with parapets at the façade and side elevations. The façade parapet is capped with a shed roof clad in Spanish clay tiles and there are three small rectangular metal vents located just under the tiles. The building roof is clad in rolled composition sheets.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking west at the façade, July 14, 2006

*P6. Date Constructed/Age and

Sources: Historic

Prehistoric Both

1938, Sutter County Assessor

*P7. Owner and Address:

Geraldo and Hilda Ramirez

2474 Archer Avenue

Live Oak, CA 95953

*P8. Recorded by: Name,

affiliation, and address)

Phyllis Smith, volunteer

Galvin Preservation Associates Inc.

1611 S. Pacific Coast Hwy. Suite 104

Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe)

Intensive

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates, 2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 2

Recorded By: Phyllis Smith ***Resource Name or #** (Assigned by recorder) 9892-94 Broadway, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

***P3a. Description:**

There are two slightly recessed storefronts located at the façade. They are mirror images of each other, and each consists of a single metal and glass door. The rest of the storefront consists of metal-sash plate-glass windows. Another entry is located on the west (rear) elevation and consists of a wood screen door. It leads into an enclosed porch with wood latticework walls. The porch is sheltered by a shed roof clad with corrugated metal.

A narrow wood fence is located between this building and the one directly to the north. There is a dirt and grass area behind this commercial building that is used for parking.

The building originally had one storefront, which has been modified and made into two. The porch located at the rear is also not original. The condition of the building is good to fair.



View looking east at the west elevation

PRIMARY RECORD

Primary # _____

HRI _____

Trinomial # _____

NRHP Status Code _____

Other Listings _____

Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 9896 Broadway, Live Oak

P1. Other Identifier: Live Oak Hall Association and North Butte Lodge No. 267 of the I.O.O.F.

***P2. Location:** Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; _____ % of _____ % of Sec _____ ; B.M. _____

c. Address 9896 Broadway City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN 06-177-002

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The commercial building at 9896 Broadway in Live Oak was constructed in 1878 in the Italianate style. The second floor of the building was originally occupied by the Live Oak Hall Association, with the North Butte Lodge No. 267 of the Independent Order of Odd Fellows (I.O.O.F.) as occupants beginning in 1911. It is built up to the property line, with the north elevation abutting against the adjacent building. The building is located on the west side of Broadway between Gum and Fir Streets. It faces east within Live Oak's historic downtown area. The Sacramento Northern lines are located to the east.


This is a two-story rectangular building. The façade is symmetrical and the building sits on a concrete foundation. It has a brick structural system and has five vertical divisions at the first floor. The building is covered by a flat roof clad with composition material. There is a stepped brick parapet located at the façade and west (rear) elevation. Each elevation has a fanlight vent with horizontal metal vents and three star-shaped anchor plates. Located just below the fanlight vent of the facade is a horizontal brick band.

(continued page 2)

***P3b. Resource Attributes:** (List attributes and codes) HP6. 1-3 story commercial building

***P4. Resources Present:** Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking west at the façade, July 14, 2006

***P6. Date Constructed/Age and Sources:** Historic Prehistoric Both
1878, Sutter County Historical Society

***P7. Owner and Address:**
Historic Live Oak Assoc. Rural
California Housing
3120 Freeboard Drive, #202
West Sacramento, CA 95691

***P8. Recorded by:** Name, affiliation, and address)
Phyllis Smith, volunteer
Galvin Preservation Associates Inc.
1611 S. Pacific Coast Hwy, Suite 104
Redondo Beach CA, 90277

***P9. Date Recorded:** April, 2006

***P10. Survey Type:** (Describe)
 Intensive Reconnaissance

***P11. Report Citation:** (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates, 2005-2007)

***Attachments:** NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 2

Recorded By: Phyllis Smith ***Resource Name or #** (Assigned by recorder) 9896 Broadway Street, Live Oak
Date: April, 2006 Continuation Update


(continued from page 1)

***P3a. Description:**

There is one large storefront located at the first floor façade. It consists of a single wood door with a large light in the center. This door has a transom with three lights located above. There are two light fixtures flanking the entrance. There is a secondary entrance located at the rear elevation. There are seven windows on the façade. They are symmetrically spaced. Those at the first floor are fixed wood display windows with a sash above with either two or four lights. There are concrete panels located below these windows. Those at the second floor are tall and narrow double-hung wood-sash with two lights per sash. There are brick hoods, linked by brick horizontal bands that extend across the entire façade width, located above these second floor façade windows. The windows at the south and west (rear) elevations are also wood and consist of a combination of casement and fixed.

There is a wood fence, a concrete paved area and concrete walkways located at the rear of the property.

Alterations to the building include cladding of the façade with a cementitious stucco, a new door at front and new light fixtures flanking it. The condition of the building is good to excellent.



View looking east at the west elevation

PRIMARY RECORD

Primary # _____

HRI _____

Trinomial # _____

NRHP Status Code _____

Other Listings Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 9904 and 9910 Broadway, Live Oak

P1. Other Identifier: North Butte Lodge No. 267 of the I.O.O.F.

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ;R _____ ; _____ % of _____ % of Sec _____ ; _____ B.M.

c. Address 9904 & 9910 Broadway City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN 06-181-035

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The commercial building at 9904 and 9910 Broadway in Live Oak was constructed in 1927 in no particular architectural style. The second floor was originally occupied by the North Butte Lodge No. 267 of the Independent Order of Odd Fellows (I.O.O.F.). It is built up to the property line, with the north and south elevations abutting against the adjacent buildings. The building is located on the west side of Broadway between Gum and Fir Streets. It faces east within Live Oak's historic downtown area. The Sacramento Northern lines are located to the east.

This is a two-story rectangular building. The façade is nearly symmetrical and the building sits on a concrete foundation. The commercial building has a brick structural system, with square anchor plates located at the west (rear) elevation. The building is covered by a flat roof clad with composition sheets. The façade has a brick parapet with a cornice, with four decorative vents just beneath the cornice. The north elevation also has a parapet. There are four plain rectangular vents with horizontal metal slats located just below the roofline at the rear elevation. There is one red brick interior chimney located near the north elevation.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking west at the façade, July 14, 2006

*P6. Date Constructed/Age and Sources: Historic Prehistoric Both 1927, Sutter County Assessor

*P7. Owner and Address: Ranjit and Raninder Singh 9910 Broadway Live Oak, CA 95953

*P8. Recorded by: Name, affiliation, and address) Phyllis Smith, volunteer Galvin Preservation Associates Inc. 1611 S. Pacific Coast Hwy. Suite 104 Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe) Intensive Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates, 2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photographic Record Other (List)

CONTINUATION SHEET

Page 2 of 2

Recorded By: Phyllis Smith ***Resource Name or #** (Assigned by recorder) 9904 and 9910 Broadway, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

***P3a. Description:**

There are three storefronts located at the first floor façade. Below the single-pane metal-sash display windows are bases clad in black ceramic tiles. Located above the display windows are leaded glass windows with colonettes in between. The storefront doors are recessed, and consist of single wood and glass doors. The entry to the second floor is located at the south end of the façade. It consists of a set of recessed double metal and glass doors. There is a large single-pane window located above this entry. Other entrances are located on the rear elevation, and consist of metal and glass doors with transoms. The façade second story windows are double-hung wood-sash with lambs tongues. Their upper sashes have multiple lights. The rear elevation also has wood-sash windows, and they are either double-hung, fixed or casement. There is one window located on the north elevation, flanked by shutters.

There are two wood fences and a paved parking area located at the rear of the property.

Alterations to the building include the replacement of all the doors. The condition of the building is good to excellent.



View looking east at the west elevation

PRIMARY RECORD

Primary # _____
HRI _____

Trinomial # _____
NRHP Status Code _____

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 9914 Broadway, Live Oak

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; _____ % of _____ % of Sec _____ ; B.M. _____

c. Address 9914 Broadway City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: 06-177-013

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The commercial building at 9914 Broadway in Live Oak was constructed in 1927 in no particular architectural style. It is built up to the property line, with the north and south elevations abutting against the adjacent buildings. The building is located on the west side of Broadway between Gum and Fir Streets. It faces east within Live Oak's historic downtown area. The Sacramento Northern lines are located to the east.

This is a one-story rectangular building. The façade is symmetrical and the building sits on a concrete foundation. The commercial building has a brick structural system and is covered by a flat roof clad with composition sheets. There are three sets of clay pipe attic vents, in clusters of three, located at the brick parapet, with coping.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking west at the façade, July 14, 2006

*P6. Date Constructed/Age and Sources:

Historic
 Prehistoric Both

1927, Sutter County Assessor

*P7. Owner and Address:

Alexander and Debra A. Alvarez

9914 Broadway

Live Oak, CA 95953

*P8. Recorded by: Name,

affiliation, and address)

Sharyl Simmons, volunteer

Galvin Preservation Associates Inc.

1611 S. Pacific Coast Hwy, Suite 104

Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe)

Intensive

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates,

2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record

Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record

Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 2

Recorded By: Sharyl Simmons ***Resource Name or #** (Assigned by recorder) 9914 Broadway Street, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

***P3a. Description:**

There is one storefront located at the façade. There are single-pane metal sash display windows, with leaded glass windows located above. The recessed entry has a single wood and glass door. The entry floor is made of scored concrete. There is another entrance located at the rear elevation at a wood addition with a shed roof. It consists of double wood doors.

There is a concrete paved area with a basketball hoop located at the rear of the property.

Alterations to the building include an addition at the rear elevation. The condition of the building is good.



View looking east at the west elevation

PRIMARY RECORD

Primary # _____
HRI _____

Trinomial # _____
NRHP Status Code _____

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 9920 Broadway, Live Oak

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; _____ % of _____ % of Sec _____ ; B.M. _____

c. Address 9920 Broadway City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: 06-177-012

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The commercial building at 9920 Broadway in Live Oak was constructed in 1924 in no particular architectural style. It is built up to the property line on the southwest corner of Broadway and Gum Street, with the south elevation abutting against the adjacent building. It faces east within Live Oak's historic downtown area. The Sacramento Northern lines are located to the east.

This is a one-story rectangular building. The façade is asymmetrical and the building sits on a concrete foundation. The commercial building has a brick structural system and is covered by a flat roof clad with composition sheets. There is a brick parapet with coping at the façade. There is a double-faced plastic backlit sign located at the the northeast corner of the building.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking west at the façade, July 14, 2006

*P6. Date Constructed/Age and Sources: Historic Prehistoric Both
1924, Sutter County Assessor

*P7. Owner and Address:
Thelma R Huddleston
P. O. Box 155
Live Oak, CA 95953

*P8. Recorded by: Name, affiliation, and address)
Sharyl Simmons, volunteer
Galvin Preservation Associates Inc.
1611 S. Pacific Coast Hwy. Suite 104
Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe)
 Intensive Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates, 2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 2

Recorded By: Sharyl Simmons ***Resource Name or #** (Assigned by recorder) 9920 Broadway Street, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

***P3a. Description:**

There is one storefront located at the façade. The recessed entry has a single wood and glass door, and an entry floor clad with clay tiles. Diagonal wood boards clad the wall section above the entrance. A secondary entrance is located at the west (rear) elevation. There is one fixed wood-sash display window at the façade. Its upper section is clad with diagonal wood boards and it has a wood sill. Other windows throughout the commercial building have been sealed with wood boards. The two windows at the rear elevation have security bars.

There is a lawn located at the rear of the property.

Alterations to the building include the sealing of the north elevation windows with wood boards, the cladding at the façade with diagonal wood boards, and the cladding of the main entry floor in clay tiles. The condition of the building is good.



View looking south at the north elevation



View looking east at the west elevation

PRIMARY RECORD

Primary # _____

HRI _____

Trinomial # _____

NRHP Status Code _____

Other Listings _____

Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 2413 Elm Street, Live Oak

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; _____ % of _____ % of Sec _____ ; B.M. _____

c. Address 2413 Elm Street City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: 06-223-008

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The single-family residence at 2413 Elm Street in Live Oak was constructed in the circa 1920s in a modest Craftsman style. The building is located near the front of the parcel, on the north side of Elm Street between Larkin Road and L Street. The residence faces south within a modest residential neighborhood.

This is a one-story residence with a rectangular floor plan. The façade is nearly symmetrical and the building sits on a concrete foundation. The residence has a wood-framed structural system and an exterior clad in horizontal wood siding. The building is covered by a moderately-pitched front-gabled roof clad in composition shingles. The moderately-overhanging eaves are open with exposed rafters. Rectangular metal attic vents are located within the roof gables. There is an attached shed-roof structure at the north (rear) elevation used to house the water heater.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking northwest at the façade, January 2, 2006

*P6. Date Constructed/Age and

Sources: Historic Prehistoric Both
1920s, visual observation

*P7. Owner and Address:

Maria Siller
2413 Elm Street
Live Oak, CA 95953

*P8. Recorded by: Name, affiliation, and address)

Laura Gallegos
Galvin Preservation Associates Inc.
1611 S. Pacific Coast Hwy. Suite 104
Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe)

Intensive
 Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates)

2005-2007

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 2

Recorded By: Laura Gallegos ***Resource Name or #** (Assigned by recorder) 2413 Elm Street, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

*P3a. Description:

The primary entrance is located at the façade. It consists of a partial-width porch sheltered by a secondary dropped front-gabled roof supported by four simple rectangular wood posts. A wood balustrade surrounds the porch; and the landing is concrete. The single door is obscured by a metal security door. A secondary entrance is located on the rear elevation and consists of a wood door. There are two windows on the façade that flank the front porch. They are double-hung wood-sash windows with wood casings and sills. The windows on the other elevations consist of double-hung wood-sash and aluminum-sash sliding windows. The windows on the west elevation and two on the east elevation have been boarded up with horizontal wood siding matching the exterior walls.

Landscaping elements include a front lawn, mature trees and shrubs. There is an attached carport on the west elevation of the residence as well as an asphalt driveway.

Alterations to the building include the removal and replacement of some of the secondary windows. Some of the window openings have been boarded up. The rear elevation entrance and the carport are also not original. The condition of the building is good to fair.



View looking northeast at the west elevation



View looking northwest at the east elevation



View looking southwest at north (rear) and east elevations

PRIMARY RECORD

Primary # _____
HRI _____

Trinomial # _____
NRHP Status Code _____

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 2452 Elm Street, Live Oak

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; _____ % of _____ % of Sec _____ ; B.M. _____

c. Address 2452 Elm Street City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: 06-224-004

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The single-family residence at 2452 Elm Street in Live Oak was constructed in 1926 in a modest Craftsman style. The building is located near the front of the parcel, on the south side of Elm Street between Larkin Road and L Street. The residence faces north within a modest residential neighborhood.

This is a one-story rectangular plan residence. The façade is nearly symmetrical and the building sits on a concrete foundation. The residence has a wood-framed structural system and an exterior clad in horizontal wood clapboard siding. The building is covered by a moderately-pitched front-gabled roof clad with composition shingles. The moderately overhanging eaves are open with exposed rafters. There is one wood vent beneath the façade gable, and likely one within the south (rear) elevation gable. There are turbine exhaust vents on the roof. There is an attached shed roof structure, at the rear of the west elevation, used to house the water heater.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking south at the façade, January 2, 2006

*P6. Date Constructed/Age and

Sources: Historic

Prehistoric Both

1926, Sutter County Assessor

*P7. Owner and Address:

Martin Gayton

2452 Elm Street

Live Oak, CA 95953

*P8. Recorded by: Name,

affiliation, and address) _____

Phyllis Smith, volunteer

Galvin Preservation Associates Inc.

1611 S. Pacific Coast Hwy. Suite 104

Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe)

Intensive

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates,

2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record

Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record

Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 2

Recorded By: Phyllis Smith ***Resource Name or #** (Assigned by recorder) 2452 Elm Street, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

***P3a. Description:**

The primary entry is located at the façade. It consists of a partial-width porch with a dropped secondary moderately-pitched front-gabled roof. The gable end is clad with horizontal wood siding, and the porch has no supports. Concrete steps and landing lead up to a single wood-paneled door with a single light. The entry also has a security door. There are two windows on the façade. They consist of double-hung wood-sash windows. The other windows are the same, although two on the east elevation are vinyl and aluminum. There is what appears to be a fixed wood-sash window on the west elevation, and both windows on this elevation have awnings.

Landscaping elements include grass, trees and shrubs. Other features include a dirt driveway, concrete walkway and a chainlink fence. In addition to the residence, the property has one shed.

Alterations to the building include one replaced window. The condition of the building is fair.



View looking southwest at the east elevation



View looking southeast at the west elevation

PRIMARY RECORD

Page 1 of 2

*Resource Name or # (Assigned by recorder) 2750 Fir Street, Live Oak

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; _____ % of _____ % of Sec _____ ; B.M. _____

c. Address 2750 Fir Street City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)
APN _____

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The garage at 2750 Fir Street in Live Oak was constructed in the circa 1910s and has no architectural style. The building is located near the front of the parcel, on the south side of Fir Street between O and DeVilbiss Streets. The garage faces north.

This one-story garage has a rectangular floor plan. The façade is asymmetrical and the building sits on a concrete foundation. The garage has a wood-framed structural system. The façade is clad with metal sheets with a pressed stone pattern, while the side elevations are clad with corrugated metal sheets. The building is covered by a steeply-pitched front-gabled roof with a stepped false front. There is a shed roof wing located at the south (rear) elevation.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking south at the façade, January 2, 2006

*P6. Date Constructed/Age and Sources: Historic Prehistoric Both
circa 1910s, visual observation

*P7. Owner and Address: unknown

*P8. Recorded by: Name, affiliation, and address) Sharyl Simmons, volunteer Galvin Preservation Associates Inc. 1611 S. Pacific Coast Hwy. Suite 104 Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe) Intensive Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates, 2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 2

Recorded By: Sharyl Simmons ***Resource Name or #** (Assigned by recorder) 2750 Fir Street, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

***P3a. Description:**

The primary entry is located at the façade. It consists of a single metal garage door. There is a pedestrian entrance on the west elevation that consists of a wood and glass door. There also appears to be another entrance on the west elevation of the rear wing. There are no windows on the façade or east elevation. The windows on the west elevation have metal sashes.

There is some patchy grass, and a concrete walkway adjacent to the west elevation. There is a carport located on the west elevation, and a single-family residence near the rear of the building.

The garage door has been replaced. The buliding is in good condition.



View looking southwest at the east elevation



View looking southeast at the west elevation

PRIMARY RECORD

Primary # _____

HRI _____

Trinomial # _____

NRHP Status Code _____

Other Listings Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) Highway 99, teepee burner between Live Oak & Yuba City

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ;R _____ ; _____ % of _____ % of Sec _____ ; _____ B.M.

c. Address Highway 99 City between Live Oak and Yuba City Zip _____

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: N/A

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The teepee burner located on Highway 99 between Live Oak and Yuba City was constructed in the circa early twentieth century. It is located at the center of its parcel on the west side of Highway 99 and the Union Pacific Railroad tracks, between McDonald and Paseo Avenues. The structure faces east within primarily agricultural area. It is associated with a lumber/planing mill, and was formerly used to burn sawdust waste from the mill.

This cone-shaped structure has a steel structural system and an exterior clad in steel sheets. It sits on a concrete foundation. The top of the teepee burner has a round metal mesh screen exhaust cover supported by steel structural supports. There is a damper stack and scaffold on the north side.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP4. Ancillary building, HP33. Farm/ranch

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking southwest, July, 2006

*P6. Date Constructed/Age and Sources: Historic Prehistoric Both circa early twentieth century, visual observation

*P7. Owner and Address: N/A

*P8. Recorded by: Name, affiliation, and address) Carol Bordeaux, volunteer Galvin Preservation Associates Inc. 1611 S. Pacific Coast Hwy. Suite 104 Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe) Intensive Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates 2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 2

*Resource Name or # (Assigned by recorder) Highway 99, teepee burner between Live Oak & Yuba City

Recorded By: Carol Bordeaux

Date: April, 2006

Continuation

Update

(continued from page 1)

*P3a. Description:

This teepee burner is part of a lumber/planing mill complex that includes wood and metal storage sheds to the north of the structure. The burner is located within a grassy area, with a chain link fence to the east that separates its property from the railroad tracks.

The condition of the structure is good. The burner is no longer being used. No alterations to the structure have been made except for the removal of the system to deliver the sawdust from the mill.



Overview looking west at the teepee burner

PRIMARY RECORD

Primary # _____

HRI _____

Trinomial # _____

NRHP Status Code _____

Other Listings _____

Review Code _____ Reviewer _____ Date _____

Page 1 of 3

*Resource Name or # (Assigned by recorder) 6931 Kent Avenue, Live Oak

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; _____ % of _____ % of Sec _____ ; B.M. _____

c. Address 6931 Kent Avenue City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: 10-120-001

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The single-family residence at 6931 Kent Avenue in Live Oak was constructed in the circa 1920s in the Craftsman style. It is near the west side of the parcel and faces west within a rural area adjacent to a road. This is related to a larger property that also encompasses an orchard (likely walnut) and a two car garage to the northeast. There are also three additional ancillary buildings (structures to the north).

This is a one-story residence with a rectangular floor plan. The façade is nearly symmetrical and the building sits on a concrete foundation; however, the front porch rests on concrete and wood posts. The residence has a wood-framed structural system and an exterior clad in horizontal wood boards. The building is covered by a moderately-pitched front-gabled roof clad with composition shingles. There is one interior brick chimney located on the slope.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking east at the façade, July 18, 2006

*P6. Date Constructed/Age and Sources: Historic Prehistoric Both circa 1920s, visual observation

*P7. Owner and Address: John J. Thomas and Nichol Nichols
P. O. Box 8223
Truckee, CA 96162

*P8. Recorded by: Name, affiliation, and address) Sharyl Simmons, volunteer
Galvin Preservation Associates Inc.
1611 S. Pacific Coast Hwy. Suite 104
Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe) Intensive Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates, 2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 3

Recorded By: Sharyl Simmons ***Resource Name or #** (Assigned by recorder) 6931 Kent Avenue, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

***P3a. Description:**

There is a porch that wraps around the building to the northern elevation. The building's porch is enclosed. The porch shares the principal roof. It appears to be an early alteration. The porch is supported by tapered wood square columns on either end of the façade. The porch appears to be partial at the façade with the south end area enclosed and made into rooms. There are two single doors within the porch. One has a paneled door and the other is wood with a single light. At the exterior of the porch is a single wood and glass door with concrete steps leading up to it. There is another single wood door at the northern elevation. The windows are either paired or triple double-hung sash windows. The windows of the enclosed porch are either double-hung wood-sash (three) or are fixed with eight lights per sash. The windows on the side elevations are double-hung wood-sash.

Landscaping elements include a lawn directly in front of the residence. There are also mature trees, including evergreens, at the street. Bushes are directly adjacent to the home. There is a concrete pathway to the front porch and also one that leads to the rear of the property. To the northeast is a two-car garage more recently built. There is an asphalt driveway leading to it. There are also three other agricultural buildings/structures located to the north that are newer and may be associated with this property.

The front porch has been enclosed. However, this is an early alteration. The northern elevation door is newer. The garage is relatively new. Of the other three ancillary buildings/structures, the one in the center appears to be from the early half of the 20th century, but the others appear newer. The condition of the building is good.

CONTINUATION SHEET

Page 3 of 3

Recorded By: Sharyl Simmons *Resource Name or # (Assigned by recorder) 6931 Kent Avenue, Live Oak
Date: April, 2006 Continuation Update



View looking southwest at the north elevation



View looking north at the south elevation



View looking east at the façade details



View looking northeast at the secondary buildings

PRIMARY RECORD

Primary # _____
HRI _____

Trinomial # _____
NRHP Status Code _____

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 2581 Kola Street, Live Oak

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; _____ % of _____ % of Sec _____ ; B.M. _____

c. Address 2581 Kola Street City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: N/A

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The single-family residence at 2581 Kola Street in Live Oak was constructed in the circa 1870s in the Italianate style. It is near the south end of the parcel and faces south at the northwest corner of Kola Street and Live Oak Boulevard.

This is a one-story residence with a rectangular floor plan. The façade is symmetrical and the building sits on a concrete foundation. The residence has a wood-framed structural system and an exterior clad in horizontal wood siding. The building is covered by a moderately-pitched hipped roof clad with composition shingles. The moderately-overhanging eaves are open with knee brackets.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking north at the façade, July 18, 2006

*P6. Date Constructed/Age and Sources:

Historic

Prehistoric Both

circa 1870s, visual observation

*P7. Owner and Address:

N/A

*P8. Recorded by: Name,

affiliation, and address)

Phyllis Smith, volunteer

Galvin Preservation Associates Inc.

1611 S. Pacific Coast Hwy. Suite 104

Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe)

Intensive

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates, 2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record

Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record

Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 2

Recorded By: Phyllis Smith ***Resource Name or #** (Assigned by recorder) 2581 Kola Street, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

***P3a. Description:**

The primary entry is located at the façade and consists of an iron security door. There are two windows on the façade. They are symmetrically spaced and consist of double-hung aluminum-sash windows. Other windows throughout the residence consist of a combination of double-hung and sliding aluminum windows.

Landscaping elements include grass, trees and shrubs. Other features include a driveway, a walkway and a small shed.

Alterations to the building include the iron door and all windows. The condition of the building is good.



View looking east at the west elevation



View looking west at the east elevation



View looking south at the north elevation

PRIMARY RECORD

Primary # _____

HRI _____

Trinomial # _____

NRHP Status Code _____

Other Listings _____

Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 2633 Kola Street, Live Oak

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; _____ % of _____ % of Sec _____ ; B.M. _____

c. Address 2633 Kola Street City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: 06-124-004

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The single-family residence at 2633 Kola Street in Live Oak was constructed in 1915 in the Craftsman style. The building is near the front of the parcel, on the north side of Kola Street between N Street and Live Oak Boulevard. The residence faces south within a neighborhood with some residences, with the Diamond Walnut Growers processing plant (facing Live Oak Boulevard) to the south.

This is a one-and-a-half story residence with a rectangular floor plan. The façade is symmetrical and the building sits on a concrete foundation. The residence has a wood-framed structural system and an exterior clad in horizontal wood board siding. The building is covered by a moderately-pitched side-gabled roof clad with composition shingles. The moderate-to-wide overhanging eaves are open with exposed rafters. There are knee brackets within the gable ends. The west gable end also has a rectangular vent. The building has one dormer, with horizontal wood board siding, located on the façade side of the roof. It consists of a gabled dormer with moderate-to-wide overhanging eaves with exposed rafters and a double-hung vinyl sash window. The dormer also has knee brackets.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking north at the façade, July 18, 2006

*P6. Date Constructed/Age and

Sources: Historic

Prehistoric Both

1915, Sutter County Assessor

*P7. Owner and Address:

Declaration Boone

6738 Larkin Road

Live Oak, CA 95953

*P8. Recorded by: Name,

affiliation, and address)

Phyllis Smith, volunteer

Galvin Preservation Associates Inc.

1611 S. Pacific Coast Hwy. Suite 104

Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe)

Intensive

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates, 2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record

Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record

Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 2

Recorded By: Phyllis Smith ***Resource Name or #** (Assigned by recorder) 2633 Kola Street, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

***P3a. Description:**

The primary entry is located at the façade. It consists of a full-width porch sheltered by the principal roof. The roof is supported by two sets of four short wood rectangular posts sitting on battered bases clad with horizontal wood boards. There are also two simple rectangular wood posts. The balustrade is clad with horizontal wood boards. Wood steps and landing lead up to a single door with a wood door surround and obscured by an iron security door. There are two windows at the façade, located within the porch and flanking either side of the front door. They each consist of two wood-sash windows; the lower sash has a large single light and the upper has twelve lights. Other windows throughout the residence consist of double-hung wood-sash windows with a single light per sash. There is a squared bay window at the east elevation. All of the windows are surrounded by casings and have lintels.

Landscaping elements include grass, mature shrubs and trees. Other features include a concrete walkway along the front and east side of the residence. There is a detached garage at the northeast section of the property, as well as a small shed to the rear of the residence. Both buildings have horizontal wood board cladding.

Alterations to the building include the addition of a security door and a new dormer window. The condition of the building is good.



View looking northeast at the west elevation



View looking northwest at the east elevation



View looking north at garage at the northeast section of the property

PRIMARY RECORD

Primary # _____

HRI _____

Trinomial # _____

NRHP Status Code _____

Other Listings _____

Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 2663 Kola Street, Live Oak

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; _____ % of _____ % of Sec _____ ; B.M. _____

c. Address 2663 Kola Street City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: 06-124-010

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The single-family residence at 2663 Kola Street in Live Oak was constructed in 1909 in the Transitional style. The building is near the front of the parcel, on the north side of Kola Street between N Street and Live Oak Boulevard. The residence faces south within a neighborhood with some residences, with the Diamond Walnut Growers processing plant (facing Live Oak Boulevard) to the south.

This is a two-story residence with a rectangular floor plan. The façade is symmetrical and the foundation is likely concrete. The residence has a wood-framed structural system and an exterior clad in horizontal wood board siding, with fishscale siding at the second-story façade. The building is covered by a moderately-pitched cross-gabled roof clad with composition shingles. The moderately-overhanging eaves are open with exposed rafters. There are knee brackets within the gable ends. The side elevation gable ends also have rectangular vents. There is an exterior red brick chimney located on the east elevation.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking east at the façade, July 18, 2006

*P6. Date Constructed/Age and

Sources: Historic

Prehistoric Both

1909, Sutter County Assessor

*P7. Owner and Address:

Ed and Mary Lou Porter

2663 Kola Street

Live Oak, CA 95953

*P8. Recorded by: Name,

affiliation, and address)

Phyllis Smith, volunteer

Galvin Preservation Associates Inc.

1611 S. Pacific Coast Hwy. Suite 104

Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe)

Intensive

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates, 2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record

Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record

Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 2

Recorded By: Phyllis Smith ***Resource Name or #** (Assigned by recorder) 2663 Kola Street, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

***P3a. Description:**

The primary entry is located at the façade. It consists of a full-width porch sheltered by a secondary dropped shed roof. There is a pediment with a sunburst design located at the center of this shed roof. The roof is supported by rectangular wood posts and there is a wood balustrade. The area just below the balustrade is clad with fishscale shingles. Wood steps and landing lead to a single wood door with a wood surround. The door itself has an oval light with a panel below. The screen door is also wood. There are four windows at the façade. Two are located within the porch, and two are at the second-story level. They are all double-hung wood-sash windows; the second-story windows have six lights per sash. Those on the other elevations are also double-hung wood-sash windows with a single light per sash. There is a squared bay window at the west elevation. All of the windows are surrounded by casings and have lintels.

Landscaping elements include grass and mature shrubs and trees. There are also two light standards, each with three round luminaries, flanking a concrete walkway at the front of the property. Other features include a gravel driveway and a detached garage. The name "Shidler" is embedded into the concrete located at street level.

There are no apparent alterations, although the light standards are not original. The condition of the building is good.



View looking northeast at the west elevation



View looking northwest at the east elevation



View looking northwest at the façade pediment



View looking north at a concrete detail in front of the property

PRIMARY RECORD

Primary # _____
HRI _____

Trinomial # _____
NRHP Status Code _____

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 9749 L Street, Live Oak

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ; R _____ ; _____ % of _____ % of Sec _____ ; B.M. _____

c. Address 9749 L St. City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: N/A

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The single-family residence located at 9749 L Street in Live Oak was constructed in the circa 1920s in the Craftsman style. It is located near the front of the parcel. The building faces west within a residential neighborhood of houses, generally dating from the 1920s and 1930s.

This is a one-story rectangular plan residence. The façade is symmetrical and the building sits on a concrete foundation. The residence has a wood-framed structural system and an exterior clad in horizontal wood boards. The building is covered by a moderately-pitched, side-gabled roof clad with composition shingles.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking east at the façade, July, 2006

*P6. Date Constructed/Age and

Sources: Historic

Prehistoric Both

circa 1920s, visual observation

*P7. Owner and Address:

N/A

*P8. Recorded by: Name, affiliation, and address)

Sharyl Simmons, volunteer
Galvin Preservation Associates Inc.
1611 S. Pacific Coast Hwy. Suite 104
Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe)

Intensive

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates 2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 2

Recorded By: Sharyl Simmons ***Resource Name or #** (Assigned by recorder) Northeast corner of L Street and Date Avenue, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

***P3a. Description:**

The primary entry is located at the façade. It consists of a porch with a gabled roof also clad in composition shingles and supported by squared wood porch supports. The porch steps and landing are concrete and the entry door is obscured by a security door. Other entries are located on the south elevation and consist of wood and glass doors. There are four windows on the façade. They are symmetrically spaced and consist of two pairs of double-hung wood-sash windows with wood-framed screens. Other windows throughout the residence consist of a combination of one aluminum-sash sliding window and double-hung wood-sash windows.

Landscaping elements include a large mature evergreen tree, two mature citrus trees, some shrubs and a front lawn. Other features include a concrete walkway bordering the front and south elevation side yards.

The condition of the building is good. Alterations to the building include the replacement of the east elevation window with an aluminum sliding window and the attachment of air conditioning unit or water cooler units to two of the south elevation windows.



View looking southeast at the north elevation



View looking northeast at the south elevation



View looking northwest at the east elevation



View looking north at the south elevation

PRIMARY RECORD

Primary # _____
HRI _____

Trinomial # _____
NRHP Status Code _____

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 3

*Resource Name or # (Assigned by recorder) 9913 L Street, Live Oak

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted *a. County Sutter

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____ ;R _____ ; _____ % of _____ % of Sec _____ ; _____ B.M.

c. Address 9913 L Street City Live Oak Zip 95953

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ; _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: 06-193-041

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The single-family residence at 9913 L Street in Live Oak was constructed in 1910 in the Craftsman style. The building is located near the front of the parcel on the east side of L Street facing west within a residential neighborhood of houses predominantly dating to circa 1920s-1930s.

This one-and-a-half story residence has a rectangular floor plan. The façade is symmetrical and the building sits on a concrete foundation. The building has a wood-framed structural system and an exterior clad in horizontal wood board siding. The building is covered by a moderately-pitched, side-gabled roof clad with composition shingles. There are knee brackets underneath the wide overhanging eaves with casement/fixed windows within each gable flanked by vents. The building has one shed roof dormer clad with composite shingles located on the façade side of the side-gabled roof. Its overhanging eaves have exposed rafters. In addition, there is a projecting section of the home with a shed roof on the south elevation.

(continued page 2)

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.):

*P5a. Photograph or Drawing (Photograph required for buildings, structures or objects)



P5b. Description of Photo: (view, date, accession #) View looking east at the façade, July 18, 2006

*P6. Date Constructed/Age and Sources: Historic Prehistoric Both
1910, Sutter County Assessor

*P7. Owner and Address:
Juan and Julie Curiel
9913 L Street
Live Oak, CA 95953

*P8. Recorded by: Name, affiliation, and address)
Sharyl Simmons, volunteer
Galvin Preservation Associates Inc.
1611 S. Pacific Coast Hwy. Suite 104
Redondo Beach CA, 90277

*P9. Date Recorded: April, 2006

*P10. Survey Type: (Describe)
 Intensive Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Sutter County Historic Survey (Galvin Preservation Associates, 2005-2007)

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure & Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photographic Record Other (List) _____

CONTINUATION SHEET

Page 2 of 3

Recorded By: Sharyl Simmons ***Resource Name or #** (Assigned by recorder) 9913 L Street, Live Oak
Date: April, 2006 Continuation Update

(continued from page 1)

***P3a. Description:**

The primary entry is located at the façade. It consists of a wood door with diamond-shaped lights (Craftsman style) in an enclosed porch, but with no screens or windows. The porch is the full width of the house and has wood stairs and landing. There are two windows on the façade. They are symmetrically spaced and consist of double-hung wood-sash windows with diamond-patterned panes on the upper sash at the front porch. The secondary entrance is at the rear addition, a single wood and glass door. Other windows throughout the single-family residence consist of a combination of double-hung sash windows with a single pane per sash and four replacement slider types.

Landscaping elements include a mature lawn and trees. Other features include decorative concrete pavers at the driveway, a concrete walkway at the northern elevation leading to the back yard, a brick walkway leading to the porch, a white picket fence at the façade and a chain link/chicken wire fence with two light posts at the rear of the property.

Alterations to the building include an addition at the rear, replaced windows on the secondary elevations, an attached exterior air conditioning unit on the northern elevation and two new light posts on the front lawn. The condition of the building is good.

Recorded By: Sharyl Simmons *Resource Name or # (Assigned by recorder) 9913 L Street, Live Oak
Date: April, 2006 Continuation Update



View looking northeast at the south elevation



View looking southwest at the north elevation



View looking southwest at the east (rear) elevation



View looking at the northeast elevation of the garage